Approved For Release 2001/08/13 : CIA-RDP78T05694A000200310001-2

S_E_C_R_E_T NOFORN

PHOTO INTELLIGENCE MEMORANDIM

STATUS OF FIVE SELECTED POL SITES _____ FOOCHON and SWATON

OP/I-103

(Project 71.174)

14 June 1955

CENTRAL INTELLIGENCE AGENCY Office of Research and Reports

S_E_C_R_E_T NOFORN

Declass Review by NIMA / DoD

Approved For Release 2001/08/13: CIA-RDP78T05694A000200310001-2

S-E-C-R-E-T NOFORN

> @/I_103 14 June 1955

STATUS OF FIVE SELECTED POL SITES _____
FOOCHON and SWATON

(Reference A: "Petroleum Facilities of China, Manchuria, and Korea" published 1945 by EOC, Office of the Quartermaster - CONFIDENTIAL)

shown on photography of

All buildings remain and appear in use, however, all storage tanks have been destroyed or the main jetty remain but there is a lack of track activity and the pierhead is gone. In addition the small boat harbor has filled with sediments and the entire area has an appearance of inactivity.

The facility of the Asiatic Petroleum Company

presents a more difficult problem. As of photography the basic pattern of structures remains the same as shown
in reference A with some removals and additions. The most noteworthy removals being the old oil storage tanks of which no
trace remains, their place having been taken by a long, low,
one-story shed-type structure. The yard tracks shown in the
reference A diagram have been removed as have buildings H, K, U,
V, and W. There is an additional long storage shed just to the

SECRET NOVORN

25X1D

25X1D

rear of the Manager's residence that runs almost the full width of the compound. The jetty remains and is in usable condition but would appear to be in use by an adjacent installation rather than the oil company.

One and only one tank appears in the photography.

It is in the general area previously occupied by building "H" and is a small round tank of the type used for highly volatile materials, approximately 20 feet in diameter.

Poochos Area:

Foochow (Up_River) Installation The Asiatic Petroleum Co. (S.C.) Ltd. (Royal Dutch Shell)

The installation is located on the north bank of the Min River, about 5000° downstream (east) from the bridge at Foocher.

The drawing of the installation in reference A represents the site as it existed some years ago.

The POL storage tanks, shown on the drawing in reference A as "A", "B", "C", and "D", do not presently exist.

The buildings shown are at present apparently intact.

The lower jetty still remains, but the upper jetty cannot be seen.

Interpretation of photography of indicates that the installation is not currently active as a fuel storage area.

S-E-C-R-E-T - NOFORN

25X1D

Approved For Release 2001/08/13 CARDR78T05694A000200310001-2

Foochow (Pagoda) Installation Standard-Vacuum Oil Co.

The installation is located on the south bank of the Min River, just across the river (south) of Ma_Wei.

The drawing of the installation in reference A is apparently accurate and represents the site as it existed some years ago. The buildings are still intact, but the full storage tanks are now gone. The earthen revetments are still in place around the tank sites. Also, the pier which contained the oil lines no longer exists.

25X1D

Photographic interpretation of photography indicates that the installation is not presently active as a fuel storage area.

Foochow (Pagoda) Installation
The Asiatic Petroleum Co. (S.C.) Ltd.
(Royal Butch Shell)

The installation is located on the south bank of
Min River, about 3500° downstream (N.V.) of the Standard-Vacuum
Oil Co. installation.

The drawing of the installation in reference A is apparently accurate and represents the site as it existed some years ago. The remnants of the buildings and tanks are still wisible on the aerial photography of

25X1D

Referring to the diagram on page 95 of reference A both the pipeline and loading jetties are now gone. Both the

S_E_C_R_E_T NOPORN gasoline and kerosene warehouses are gone. Tank "C" is not visible. Tank "D" remains, apparently intact. Tank "A" is visible, but only the shell is intact. Tank "B" is gone, and only the niche in the hillside is visible. The large building on the ridge to the WNV of tank "A" is visible, but only the unroofed walls remain.

Photographic interpretation indicates that the installation is not presently active as a fuel storage area.

S_L_C_R_E_T NOFORN